Notice



CORRECTION PRODUCTION CHANGE	
SERVICE FLASH ADD INFORMATION	FILE NO.
Please add this notice to the Service Manual listed below.	REVISION 0
Category: COLOR TELEVISION Date	e: FEBRUARY / 07 / 2012
Model: DP42841 Effective from : 0	Chassis No. P42841-13
Destination: U.S.A. / CANADA REF : No. SM780194-13	
NOTE: Match the Chassis No. on the unit's back cover with the	e Chassis No. in the Service
Manual. If the Service Manual Chassis No. does not match Literature is required. This chassis is similar to Chass	the unit's, additional Service

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

difference Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual for Chassis No. P42841-10 and **Notices** for Chassis

1. IN THE SERVICE ADJUSTMENTS

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

No. P42841-11 used in Model DP42841 (SM780194).

The are no changes.

3. PWR ON LED POSITION CHANGE

Before (Z5VK): Right side Current (Z5VKE): Left side

For parts or service contact:

Sanyo Manufacturing Corporation 2012

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

February 2012 SMC

DP42841, Z5VKE PRODUCT CODE 113026406

Published in Mexico

REFERENCE No. SM780194-13